



Phottix Odin TTL Flash Trigger for Sony

Firmware Version V1.14

Change Log

March 16, 2015

1. Modified the issue that when used on A99, flash can't be triggered after adjusting ISO through a cycle.
2. Modified the issue that when used on A57, F60 does not fire by pressing the test button on TCU while the camera is in sleep mode.
3. Modified the issue that Odin TCU can't turn off the group using Strato II.
4. Test Button and Light Meters: Pressing the Test button on the transmitter will cause the flashes in A, B and C groups to fire simultaneously. Group(s) turned off will not fire.

When the flashes in A, B and C groups are set to Manual (M) mode, pressing the Test button on the transmitter will cause the flashes (which are powered on and on the same channel as the transmitter) to fire an initial low-power pre-flash. The flashes will fire simultaneously at their set manual power levels 2.5s later. This feature allows for light meters to be used correctly.

Phottix TTL触发器 for Sony (Odin)

固件版本V1.14

更改记录

2015年03月16日

1. 修改了A99相机ISO转一周后就不能引闪的问题。
2. 修改了A57相机睡眠按TEST按键F60闪光灯不闪光的问题。
3. 修改了ODIN A,B,C处于OFF状态还能引闪Strato II 的问题，
4. Test按钮和测光表测光：发射器TEST键的功能改为A B C三组一起闪光（关闭的组不会闪光），用于测光表测光；在A B C三组都为M模式时，按一下发射器上的TEST按钮，所有开启的与发射器处于同一频道的闪光灯将以比较低的功率预闪一次，2.5秒后再按事先设定好的功率值闪光。此闪光可用于测光表测光；